

## User manual IM3

## Strain gauge amplifier with a calibration for 350 Ohm melt pressure sensors



#### **Technical features:**

- red display of -19999...99999 digits (optional: green, orange or blue display)
- installation depth: 120 mm without plug-in terminal
- min/max memory
- 30 parameter driven setpoints
- optical threshold value indication at threshold value exceedance / undercut
- [O]-key for triggering of Hold, Tara or sensor alignment
- digital input for triggering of Hold, Tara or sensor alignment
- permanent min/max-value recording
- sensor alignment with integrated switching output
- mathematical functions like e.g. reciprocal value, square root, squaring or rounding
- sliding averaging
- brightness control
- programming interlock via access code
- protection class IP65 at the front
- plug-in terminal
- option: 1 or 2 analog outputs
- option: 2 or 4 relay outputs or 8 PhotoMos outputs
- option: interface RS232 or RS485
- accessories: PC-based configuration kit PM-TOOL incl. CD and USB-adapter for devices without keypad and for a simple adjustment of standard devices


Tel.: 03303 / 504066

Fax: 03303 / 504068

#### Identification

STANDARD-TYPES	ORDER NUMBER
Strain gauge	IM3-1MR5B.020X.570BD
Housing size: 96x48 mm	IM3-1MR5B.020X.670BD

#### Options - break-down product key:



Please state physical unit by order, e.g. m/min.

# Contents

1.	Brief description	2
2.	Assembly	3
3.	Electrical connection	4
4.	Function description and operation	5
	4.1. Programming software PM-TOOL	6
5.	Setting up the device	7
	5.1. Switching on	7
	5.2. Standard parameterisation (flat operation level)	7
	Value assignment for the triggering of the signal input	
	5.3. Programming interlock " <i>RUท</i> "	10
	Activation/Deactivation of the programming interlock or change into professional or flat operation level	
	5.4. Extended parametersation (professional operation level)	11
	5.4.1. Signal input parameters "IMP"	11
	Value assignment for the triggering of the signal input incl. linearisation	
	5.4.2. General device parameters "FLT"	14
	Superior device functions like Hold, Tara, min/max permanent, averaging, brightness control,	
	as well as the control of the digital input and keyboard layout	
	5.4.3. Safety parameters "COD"	17
	Assignment of user and master code to lock or to receive access to defined parameter such as analog output and alarms, etc.	
	5.4.4. Serial parameters "SER"	19
	Parameter for interface definition	
	5.4.5. Analog output parameters "OUT"	20
	Analog output functions	
	5.4.6. Relay functions "REL"	23
	Parameter for setpoint definition	
	5.4.7. Alarm parameters "RL1RL4"	25
	Actuator and dependencies of the alarms	
6.	Reset to factory settings	27
	Reset parameters onto the delivery state	
7.	Alarms / Relays	28
	Functional principle of the switching outputs	
8.	Interfaces	29
	Connection RS232 and RS485	
9.	Sensor aligment	30
	Diagram of functional sequences for sensors with existing adjustable resistor	
10.	Technical data	31
11.	Safety advices	33
12.	Error elimination	34

## 1. Brief description


The panel meter **IM3-1M** is a 5-digit device for connection to a 4-wire-measuring bridge with calibration contact (80% alignment) and a visual threshold value monitoring via the display. The configuration happens via four front keys or via the optional PC software PM-TOOL. An integrated programming interlock prevents unrequested changes of the parameters and can be unlocked again by an individual code. Optional the following functions are available: a 10 V bridge feeding, a digital input for the triggering of Hold (Tara) or the 80%-alignment, two analog outputs, one interface, as well as two or four galvanic isolated setpoints, by which free adjustable threshold values can be controlled and reported to a superior master display.

The electrical connection is carried out on the back side via plug-in terminals.

Selectable functions like e.g. the request of the min/max-value, an average determination of the measuring signals, a direct change of threshold value in operation mode and additional measuring supporting points for linearisation complete the modern device concept.

# 2. Assembly

Please read the Safety advices on page 33 before installation and keep this user manual for future reference.




- 1. After removing the fixing elements, insert the device.
- 2. Check the seal to make sure it fits securely.
- 3. Click the fixing elements back into place and tighten the clamping screws by hand. Then use a screwdriver to tighten them another half a turn.

CAUTION! The torque should not exceed 0.1 Nm!


The dimension symbols can be exchanged before installation via a channel on the side!

## 3. Electrical connection


**Type IM3-1MR5B.020X.470BD** supply of 115 VAC **Type IM3-1MR5B.020X.570BD** supply of 230 VAC **Type IM3-1MR5B.020X.670BD** supply of 10-30 VDC



M3 with digital input in combination with 24 VDC sensor supply



M3 with digital input and external voltage source



## 4. Function and operation description

#### Operation

The operation is divided into three different levels.

#### Menu level (delivery status)

This level was designed for the standard settings of the device. Only menu items which are sufficent to set the device into operation are displayed. To get into the professional level, run through the menu level and parameterise **PROF** under menu item **RUN**.

#### Menu group level (complete function volume)


Suited for complex applications as e.g. linkage of alarms, setpoint treatment, totaliser function etc. In this level function groups which allow an extended parameterisation of the standard settings are availabe. To leave the menu group level, run through this level and parameterise **ULDC** under menu item **RUN**.

#### Parameterisation level:

Parameter deposited in the menu item can here be parameterised. Functions, that can be changed or adjusted, are always signalised by a flashing of the display. Settings that are made in the parameterisation level are confirmed with **[P]** and thus saved. Pressing the **[O]-key** leads to a break-off of the value input and to a change into the menu level. All adjustments are saved automatically by the device and changes into operating mode, if no further key operation is done within the next 10 seconds.

Level	Key	Description
	Р	Change to parameterisation level and deposited values.
Menu-level		Keys for up and down navigation in the menu level.
	0	Change into operation mode.
Parameterisation- level	Р	To confirm the changes made at the parameterization level.
		Adjustment of the value / the setting.
	0	Change into menu level or break-off in value input.
	Р	Change to menu level.
Menu-group-level		Keys for up and down navigation in the menu group level.
	0	Change into operation mode or back into menu level.

#### Function chart:



#### Underline:

- P Takeover
- O Stop
- ▲ Value selection (+)
- Value selection (-)

### 4.1 Parameterisation software PM-TOOL:

Part of the PM-TOOL are the software on CD and an USB-cable with device adapter. The connection happens via a 4-pole micromatch-plug on the back side of the device, to the PC-side the connection happens via an USB plug.

System requirements: PC incl. USB interface Software: Windows XP, Windows VISTA

With this tool the device configuration can be generated, omitted and saved on the PC. The parameters can be changed via the easy to handle program surface, whereat the operating mode and the possible selection options can be preset by the program.

#### **CAUTION!**

During parameterisation with connected measuring signal, make sure that the measuring signal has no mass supply to the programming plug. The programming adapter is galvanic not isolated and directly connected with the PC. Via polarity of the input signal, a current can discharge via the adapter and destroy the device as well as other connected components!

## 5. Setting up the device

### 5.1. Switching on


Once the installation is complete, start the device by applying the voltage supply. Before, check once again that all electrical connections are correct.


#### Starting sequence


For 1 second during the switching-on process, the segment test (**B B B B B**) is displayed followed by an indication of the software type and, after that, also for 1 second the software version. After the starting sequence, the device switches to operation/display mode.


## 5.2. Standard parameterisation: (Flat operation level)

To parameterise the display, press the **[P]**-key in operating mode for 1 second. The display then changes to the menu level with the first menu item **TYPE**.













### **5.4. Extended parametrisation** (Professional operation level)

#### 5.4.1. Signal input parameters














### 5.4.2. General device parameters















## 5.4.3. Safety parameters










### 5.4.4. Serial parameters







### 5.4.5. Analog output parameters for analog output 1










## Analog output parameters for analog output 2










### 5.4.6. Relay functions












## 5.4.7. Alarm parameters








The same applies for RL2 to RL8.

## Programming interlock, RUM:



Description see page 10, menu level RUN

## 6. Reset to factory settings

To return the unit to a **defined basic state**, a reset can be carried out to the default values. The following procedure should be used:

- Switch off the power supply
- Press button [P]
- Switch on voltage supply and press [P]-button until "----" is shown in the display.


With reset, the default values of the program table are loaded and used for subsequent operation. This puts the unit back to the state in which it was supplied.

Caution! All application-related data are lost.

## 7. Alarms / Relays


This device has 4 virtual alarms that can monitor one limit value in regard of an undercut or exceedance. Each alarm can be allocated to an optional relay output S1-S4; furthermore alarms can be controlled by events like e.g. Hold or min/max-value.

Function principle of alarms / relays		
Alarm / Relay x	Deactivated, instantaneous value, min/max-value, hold-value, sliding average value or an activation via the digital input	
Switching threshold	Threshold / limit value of the change-over	
Hysteresis	Broadness of the window between the switching thresholds	
Working principle	Operating current / quiescent current	




### **Operating current**

By operating current the alarm S1-S4 is **off** below the threshold and **on** on reaching the threshold.



#### **Quiescent current**

By quiescent current the alarm S1-S4 is **on** below the threshold and switched **off** on reaching the threshold.



#### Switching-on delay

The switching-on delay is activated via an alarm and e.g. switched 10 seconds after reaching the switching threshold, a short-term exceedance of the switching value does not cause an alarm, respectively does not cause a switching operation of the relay. The switching-off delay operates in the same way, keeps the alarm / the relay switched longer for the parameterised time.

## 8. Interfaces RS232 and RS485

### **Connection RS232**


## Digital device M3

### PC - 9-pole Sub-D-plug



### **Connection RS485**


## Digital device M3



The interface **RS485** is connected via a screened data line with twisted wires (Twisted-Pair). On each end of the bus segment a termination of the bus lines needs to be connected. This is neccessary to ensure a secure data transfer to the bus. For this a resistance (120 Ohm) is interposed between the lines Data B (+) and Data A (–).

## 9. Sensor alignment offset / final value

The device has an automatic calibration at mass pressure sensors, where an integrated switching output operates an often available 80% calibration. Like this offset and final value are adjusted, and the sensor can be applied directly after this. The calibration can be done via the 4th key or the digital input, depending on the parameterisation.



If a special input range **SENS.1**, **SENS.2**, **SENS.3** was selected under **TYPE**, a checking of the range is done for offset and final value. At an undercut/exceedance of +/- 20% of adjustment range, an **C.FRIL** is given out.

# 10. Technical data

Housing		
Dimensions	96x48x120 mm (BxHxD)	
	96x48x139 mm (BxHxD) incl. plug-in terminal	
Panel cut-out	92.0 <sup>+0,8</sup> x 45.0 <sup>+0,6</sup> mm	
Wall thickness	to 15 mm	
Fixing	screw elements	
Material	PC Polycarbonate, black, UL94V-0	
Sealing material	EPDM, 65 Shore, black	
Protection class	standard IP65 (Front), IP00 (Back side)	
Weight	approx. 300 g	
Connection	plug-in terminal; wire cross section up to 2.5 mm <sup>2</sup>	
Display		
Digit height	14 mm	
Segment colour	red (optional blue/green/orange)	
Range of display	-19999 to 99999	
Setpoints	one LED per setpoint	
Overflow	horizontal bars at the top	
Underflow	horizontal bars at the bottom	
Display time	0.1 to 10.0 seconds	
Input		
Sensor sensitivity	1mV/V, 2mV/V, 3.3mV/V	
Measuring bridge	250-500 Ω / 20-40 mA	
Measuring error	<ul><li>0.2% of measuring range in electromagnetic dominated environment,</li><li>1% of measuring range in industrial invironment with strong disturbing source</li></ul>	
Digital input	< 24 V OFF, 10 V ON, max. 30 VDC $R_{I} \sim 5 \text{ k}\Omega$	
Sensor calibration	always required	
Accuracy		
Temperature drift	100 ppm / K	
Measuring time	0.110.0 seconds	
Measuring principle	U/F-converter	
Resolution	approx. 18 bit at 1s measuring time, 3.3 mV/V measuring range	

Output		
Analog output	0/4-20 mA / burden 350 $\Omega$ or 0-10 VDC / 10 k $\Omega$ , 16 bit	
Switching outputs		
Relay with change-over contacts Switching cycles	250 VAC / 5 AAC; 30 VDC / 5 ADC 30 x 10³ at 5 AAC, 5 ADC ohm resistive load 10 x 10⁶ mechanically Diversity according to DIN EN50178 / Characteristics according to DIN EN60255	
PhotoMos outputs	8 normally open (NO) contacts 30 VDC/AC, 0.4 A	
Interface		
Protocol	Modbus with ASCII or RTU-protocol	
RS232	9.600 Baud, no parity, 8 databit, 1 stopbit, wire length max. 3 m	
RS485	9.600 Baud, no parity, 8 databit, 1 stopbit, wire length max 1000 m	
Power supply	230 VAC ± 10 % max. 10 VA 10-30 VDC galv. isolated, max. 4 VA	
Memory	EEPROM	
Data life	≥ 100 years at 25°C	
Ambient conditions		
Working temperature	0°50°C	
Storing temperature	-20°80°C	
Climatic density	relative humidity 0-80% on years average without dew	
	T	
EMV	EN 61326	
CE-sign	Conformity to directive 2014/30/EU	
Safety standard	according to low voltage directive 2014/35/EU EN 61010; EN 60664-1	

## 11. Safety advices

Please read the following safety advices and the assembly *chapter 2* before installation and keep it for future reference.

### Proper use

The **IM3-1M-device** is designed for the evaluation and display of sensor signals.



Attention! Careless use or improper operation can result in personal injury and/or cause damage to the equipment.

#### Control of the device

The panel meters are checked before dispatch and sent out in perfect condition. Should there be any visible damage, we recommend close examination of the packaging. Please inform the supplier immediately of any damage.

#### Installation

The **IM3-1M-device** must be installed by a suitably **qualified specialist** (e.g. with a qualification in industrial electronics).

#### Notes on installation

- There must be no magnetic or electric fields in the vicinity of the device, e.g. due to transformers, mobile phones or electrostatic discharge.
- The fuse rating of the supply voltage should not exceed a value of 0.5A N.B. fuse!
- Do not install inductive consumers (relays, solenoid valves etc.) near the device and suppress any interference with the aid of RC spark extinguishing combinations or free-wheeling diodes.
- Keep input, output and supply lines separate from one another and do not lay them parallel with each other. Position "go" and "return lines" next to one another. Where possible use twisted pair. So, you receive best measuring results.
- Screen off and twist sensor lines. Do not lay current-carrying lines in the vicinity. Connect the **screening on one side** on a suitable potential equaliser (normally signal ground).
- The device is not suitable for installation in areas where there is a risk of explosion.
- Any electrical connection deviating from the connection diagram can endanger human life and/or can destroy the equipment.
- The terminal area of the devices is part of the service. Here electrostatic discharge needs to be avoided. Attention! High voltages can cause dangerous body currents.
- Galvanic isolated potentials within one complex need to be placed on an appropriate point (normally earth or machines ground). So, a lower disturbance sensibility against impacted energy can be reached and dangerous potentials, that can occur on long lines or due to faulty wiring, can be avoided.

# 12. Error elimination

	Error description	Measures
1.	The unit permanently indicates overflow.	<ul> <li>The input has a very high measurement, check the measuring circuit.</li> <li>With a selected input with a low voltage signal, it is only connected on one side or the input is open.</li> <li>Not all of the activated setpoints are parameterised. Check if the relevant parameters are adjusted correctly.</li> <li>An absolutely incorrect alignment has been done bevor, e.g. without connected sensor. In this case a reset to the factory setting should be carried out.</li> </ul>
2.	The unit permanently shows underflow.	<ul> <li>The input has a very low measurement, check the measuring circuit.</li> <li>With a selected input with a low voltage signal, it is only connected on one side or the input is open.</li> <li>Not all of the activated setpoints are parameterised. Check if the relevant parameters are adjusted correctly.</li> <li>An absolutely incorrect alignment has been done bevor, e.g. without connected sensor. In this case a reset to the factory setting should be carried out.</li> </ul>
3.	The word <i>HELP</i> lights up in the 7-segment display.	The unit has found an error in the configuration memory. Perform a reset on the default values and reconfigure the unit according to your application.
4.	Program numbers for parameterising of the input are not accessible.	Programming lock is activated     Enter correct code
5.	ERR1 lights up in the 7-segment display	Please contact the manufacturer if errors of this kind occur.
6.	The device does not react as expected.	• If you are not sure if the device has been parameterised before, then follow the steps as written in <i>chapter 6</i> and set it back to its delivery status.