



Portable Pressure Source Model PPS1100



Description

The Portable Pressure Source PPS1100 offers quick, efficient, and accurate means for checking pressure transducers in the field. To preform a pressure transducer test, simply remove the transducer from the process and install it in the pressure port on the PPS1100 manifold. Turn the PPS110 on and select the required engineering unit. Adjust zero and pump the pressure source until the desired pressure readout on the PPS1100 to the pressure transducer readoput to verify the transducer's accuracy.

Features


Tel.: 03303 / 50 40 66

Fax.: 03303 / 50 40 68

- Rugged but easy to carry
- Weight 3.9 kg only
- Accuracy +/- 0.1%
- Battery powered > 200 days
- Multiple pressure adaptors available
- Pressure range of 0 700 bar
- Switch selectable bar / PSI / kPA
 Memory function up to 900 measurements
- without function up to 500 med
- Serial communication
- Various display and test functions

Technical Data / Operating Data	
Pressure Range:	0 - 700 bar
Units:	ar / PSI / kPA / mH ₂ 0
Pressure Port:	1/2" 20UNF others on request
Accuracy:	+/- 0.1% f.s.v.
Resolution:	100 mbar
Sample Rate:	500 ms
Memory:	900 positions (8000 optional)
Oil Volume:	57 ml (HLP 22 BP)
Battery:	3.6 V Lithium
Battery Life:	> 200 days
Operating Temperature:	0 °C to + 50 °C
Dimensions (DxWxH):	315 x 153 x 205 mm
Weight:	3.9 kg

Order Specifications




One adapter 1/2" 20UNF 2B is included at no additional charge. Other pressure ports on request.

Dimensions

Model PPS1100

Dimensions (D x W x H)

315 x 153 x 205 mm



Tel.: 03303 / 50 40 66

Fax.: 03303 / 50 40 68